

3.785 LITERS



REG. U. S. PAT. OFF.

LUCARNE®

Exterior Enamel

MEDIUM GLOSS · DRIES IN AN HOUR · WATER CLEAN-UP



WILLOW GREEN 1802 c

COLOR SPOT INDICATES COLOR AND GLOSS

ONE GALLON

COMPOSITION

ENG 4122	Pigment 11%	Ferrite Yellow	11%
		Copper Phthalocyanine Blue	trace
		Carbon Black	trace
	Vehicle 89%		
	Plasticized Acrylic Resin	29%	
	Water	60%	
	315-504	55910	100%



LUCITE® Exterior Enamel

... the Work Skipper

A New Latex Medium-Gloss Enamel

The Perfect Trim Enamel For LUCITE® House Paint

- Easiest-to-use paint for outside wood or metal trim
- Needs no primer in most cases
- Dries smooth in an hour
- Durable, resists fading and mildew
- Clean up with soap and water

CAUTION!

Do not take internally
Close container after each use.
KEEP FROM CHILDREN

- **WHERE TO USE THIS ENAMEL** Goes on fast and smooth over exterior wood or metal trim, doors, windows, shutters, fences, posts, railings, and ornamental trim. Not recommended for siding. For siding, use LUCITE House Paint.
- **HOW MUCH YOU WILL NEED** One gallon covers about 450 square feet on smooth surfaces. One coat may suffice on sound painted surfaces but two coats give best appearance and durability. Apply two or three coats over bare or badly worn surfaces.
- **WHAT TO PAINT WITH** To get best job, use only top quality tools. For windows and narrow trim, use a 2" nylon sash brush. For broad areas, use a larger nylon brush or a medium-nap roller.



Here's how to get your best-looking, fastest job:

A - PREPARE THE SURFACE

- For good adhesion, surface must be clean, firm, and chalk-free. Scrape off peeling paint, fill holes and cracks with proper patching material, sand smooth. Seal knots and sap streaks with shellac.
- Hose off all loose dirt. Where present, wash off chalk, mildew and glossy areas with solution of detergent-bleach ($\frac{2}{3}$ cup trisodium phosphate such as Soilax, $\frac{1}{2}$ cup nonammoniated detergent, 1 qt. household bleach, 1 to 2 gal. water). In every case, underside of eaves and porch ceilings must be washed with same solution. Rinse well with garden hose.
- Remove all rust from metal surfaces.

B - EXCEPTIONS TO NO-PRIMING RULE

No primer is needed on bare wood and sound painted wood or metal, except as follows

- Bare staining woods, such as redwood, cedar, mahogany or fir plywood require two coats of LUCITE 51 Latex Wood Primer
- Bare metal surfaces require one coat of DUCO® 370 Fast-Dry Latex Primer

C - NOW FINISH WITH LUCITE EXTERIOR ENAMEL

- Ready to use. You add nothing. If thinning is ever needed, use a little water. Some stirring may be needed. Apply full, even coats. Don't spread thin.
- One coat may suffice on sound painted surfaces, but two coats are recommended. Apply two coats on primed surfaces and two or three coats on bare or badly worn surfaces.
- Dries to touch in one hour. Let dry two hours between coats, longer on humid or cool days. May paint over damp surfaces but not during rain. Stop painting at least two hours before you expect heavy dew or a temperature drop below 50°

D - CLEAN UP WITH SOAP AND WATER

Wipe off any smears or spills immediately with damp cloth or sponge. Soon as you're done painting, wash out brushes and tools.

3T-32A-010-1070